

Oil Field Environmental Incident Summary

Incident: 20150801110029 **Date/Time of Notice:** 08/01/2015 11:00

Responsible Party: Almers Construction

Well Operator: EOG RESOURCES, INC.

Well Name: LONG 1-01H

Field Name: PARSHALL

Well File #: 16637

Date Incident: 7/31/2015 **Time Incident:** 14:48

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 1

Qtr:

Location Description: The Long 1-01H is nearest associated facility to this EOG pipeline ROW (West of the Long 1-01H facility within the EOG ROW along west side of 73rd Ave NW). Open EOG ROW pipeline trench

Submitted By: Danielle Dupay

Received By:

Contact Person: Merle Almer
PO Box 63
Tioga, ND 58852

General Land Use: Other - Described Above

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	5	Barrels	5	Barrels	5	barrels
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 10/27/2015 **Clean Up Concluded:** 8/3/2015

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

A vac truck was called immediately to remove liquids, a hydrovac then removed the saturated material and a track hoe removed remaining solid material.

Wastes Disposal Location: Liquids were taken to SWD, Solids were taken to Clean Harbors, Sawyer, ND

Agencies Involved:

Updates

Date: 8/3/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release on pipeline ROW. Followup is required.

Date: 9/1/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 10:23 9/1/2015.

Work continues along the pipeline right of way, and vac truck is present at location. Minimal impact to area with the spill remaining in the excavation.

More followup is necessary to ensure proper cleanup.

Date: 4/18/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated April 18, 2016.